



Inspection/Final Report

Client	: Cartwright International Van Lines, INC	Adjuster	: Shelby Hessel
Adjuster Ph	:	Date Received	: Nov 04, 2022
GBL#	: BGAC0605693	Estatus Ref #	: 660641
Valuations	: FVP	Admin	: Jeff Schatzman
Shipper	: Blake Whatley	Additional Information	:
Home Ph	:	Cell Ph	:
Work Ph	:	E-Mail	:
Address	: Fort Rucker AL		

Items List

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 1 Inv#: 157 Wt: 0 Ctn Avail: No	 	wood coffee table	Custom made table has screws at hinges stripped out for bottom door. We can repair by adding new screws and can fill, sand, and stain the damaged areas as needed to repair to industry standards.	Est: 300.00 C/S: 0.00 Fee: 0.00
SI No: 2 Inv#: 229 Wt: 0 Ctn Avail: No	  	LG gas grill/Smoke Hollow 4 in 1 grill	Grill has bottom storage with bent frame and back of plate by hinge bent. Cust straightened back as much he could to be able to use. This item shows a good bit of rust and wear, the shelf bending in transit is inherent vice due to the worn metal and rust that is present. This grill retails for \$366.47 https://www.homedepot.com/p/Smoke-Hollow-4-Burner-Propane-and-Charcoal-Grill-in-Black-SH19033319/315667031	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 3 Inv#: 60 Wt: 0 Ctn Avail:	 	Ashley 9 drawer dresser	Dresser has scars and dents on front top trim/edge and around to the lsf, this is transit related damage. We can fill, sand, and stain the damaged areas to	Est: 300.00 C/S: 0.00 Fee: 0.00

No



Image3

repair to industry standards.

Inspection/Final Report

Date of Report	:	Date Completed	:
Type of Report	:	Expenses	: \$ 0.00
Inspection Fee	:	Tax	: \$ 0.00
Total C/S	:	Total Est	: \$ 600.00
Fees	:	Total	: \$ 0.00
Additional information	:		