










Inspection/Final Report




Client	: Unigroup / Mayflower /United	Adjuster	: Team 4 Claims
Adjuster Ph	: 855-252-8913	Date	: Dec 12, 2022
Order For Service #	: 2835-01106-2	Received	
Valuations	: FVP	Estatus Ref #	: 663055
Shipper	: Kelly Runkle	Admin	: Jeff Schatzman
Home Ph	:	Additional Information	:
Work Ph	:	Cell Ph	:
Address	: Meridianville AL	E-Mail	:




Items List



#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 1 Inv#: 88 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3	1920 Waterfall Vanity	Glass completely broken in transit on the vanity mirror. A new mirror could be custom made to fit the frame. We would need a 3rd party glass service to look at the item to determine repairability and cost. This item was DBO at origin.	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 2 Inv#: 295 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3	Primary Bedroom Large Brown Dresser	Middle left drawer of dresser has separated at the face and side, we can repair it by gluing the joint back together. There was PED noted stating the drawer was broken on this item at origin, we cannot say this is new transit related damage.	Est: 125.00 C/S: 0.00 Fee: 0.00
SI No: 3 Inv#: 104 Wt: 0 Ctn Avail:	 Image1  Image2	The Beatles Wall Clock	Hand on clock face was bent in transit, the clock won't work correctly.	Est: 0.00 C/S: 14.99 Fee: 0.00




No				
	Image3			






SI No: 4		Illinois State Clock	Second hand bent in transit.	Est: 0.00
Inv#: NA				C/S: 14.99
Wt: 0				Fee: 0.00
Ctn Avail: No	Image1			


SI No: 5			Martin Guitar Backpacker	The wooden base is cracked, PED unknown for this item, item is not listed on the inventory report, we cannot say this is new transit related damage.	Est: 0.00
Inv#: 115					C/S: 0.00
Wt: 0					Fee: 0.00
Ctn Avail: No	Image1	Image2			
					
	Image3				
				Retails: \$299.00 https://www.sweetwater.com/c600--6String	

SI No: 6			Dual Record Turntable	Dual 1229 turntable. Front wooden frame is broken, this is PED. Lid cracked in corner; this doesn't appear to be fresh transit damage. This item was previously repaired as shown by the dried glue along the edge of the trim piece, this is inherent vice.	Est: 0.00
Inv#: 41					C/S: 0.00
Wt: 0					Fee: 0.00
Ctn Avail: No	Image1	Image2			
					
	Image3				
				Retails: \$212.99 https://www.ebay.com/itm/154861422310	

SI No: 7			White Bedroom Shelf	Front right corner cracked. This is new transit damage, not repairable.	Est: 0.00
Inv#: NA					C/S: 24.99
Wt: 0					Fee: 0.00
Ctn Avail: No	Image1	Image2			

SI No: 8			Black Floor Lamp	Top of lamp bent and cracked. This is new transit damage, not repairable. Similar: 44.99	Est: 0.00
Inv#: 199					C/S: 44.99
Wt: 0					Fee: 0.00
Ctn Avail: No	Image1	Image2			
					
	Image3				
				https://www.lowes.com/pd/Brigtech/5013302489	

<p>SI No: 9 Inv#: NA Wt: 0 Ctn Avail: No</p>	 Image1  Image2  Image3  Image4  Image5	<p>Chandelier Pendant Light (set of 2)</p>	<p>Base bent on both lamps in transit, not repairable.</p>	<p>Est: 0.00 C/S: 100.00 Fee: 0.00</p>
<p>SI No: 10 Inv#: 189 Wt: 0 Ctn Avail: No</p>	 Image1  Image2	<p>Extra Large Cat Box</p>	<p>Petco jumbo litter box has a broken top, this is transit damage. Retails: \$39.99 https://www.petco.com/shop/en/petcostore/product/hagen-catit-jumbo-hooded-litter-box-in-gray-1371274</p>	<p>Est: 0.00 C/S: 39.99 Fee: 0.00</p>
<p>SI No: 11 Inv#: 251 Wt: 0 Ctn Avail: No</p>	 Image1  Image2	<p>Gray Plastic Child Gate</p>	<p>Toddler Roo plastic gate. Connection pieces on right side snapped off in transit. Similar: \$24.99 https://www.target.com/p/regalo-plastic-expandable-safety-gate/-/A-75557012#lnk=sametab</p>	<p>Est: 0.00 C/S: 24.99 Fee: 0.00</p>
<p>SI No: 12 Inv#: 249 Wt: 0 Ctn Avail: No</p>	 Image1  Image2	<p>Tan Plastic Child Gate</p>	<p>Right corner Locking mechanism snapped off in transit. Retails: \$24.99 https://www.target.com/p/regalo-plastic-expandable-safety-gate/-/A-75557012#lnk=sametab</p>	<p>Est: 0.00 C/S: 24.99 Fee: 0.00</p>
<p>SI No: 13 Inv#: NA Wt: 0 Ctn Avail: No</p>	 Image1  Image2  Image3	<p>Child Wood Gate</p>	<p>Getting crushed in transit. Retails: \$14.99 https://www.evenflo.com/products/position-and-lock-baby-gate</p>	<p>Est: 0.00 C/S: 14.99 Fee: 0.00</p>

SI No: 14 Inv#: NA Wt: 0 Ctn Avail: No	 Image1  Image2  Image3	Patio Table with Umbrella	Front right leg bent outward, this is new transit damage, there was no PED for this item. Similar: \$89.00 https://www.amazon.com/Tangkula-Outdoor-Balcony-Poolside-Weather/dp/B071FKLTKP/ref=sr_1_19	Est: 0.00 C/S: 89.00 Fee: 0.00
SI No: 15 Inv#: NA Wt: 0 Ctn Avail: No	 Image1  Image2	Ryobi Lawn Mower Bag	Rip in right side of ryobi clippings bag catcher, transit related. Replacement: \$47.20 https://www.amazon.com/Ryobi-P1102-Genuine-Replacement-970699001/dp/B092MSJ29P/ref=sr_1_9	Est: 0.00 C/S: 47.20 Fee: 0.00
SI No: 16 Inv#: NA Wt: 0 Ctn Avail: No	 Image1  Image2  Image3  Image4	Glass TV Stand	Shelf is broken from the right base portion; the piece is warped at the screw canâ€™t hold weight. This is transit related damage, not repairable. Similar: \$350.00 https://www.walmart.com/ip/Z-Line-ZL950260M29-Baltic-3-in-1-TV-Stand-Mount-System/52101582	Est: 0.00 C/S: 209.49 Fee: 0.00
SI No: 17 Inv#: 024 Wt: 0 Ctn Avail: No	 Image1  Image2	Crystal Long Stem Red Rose	Leaf pedal broken off in transit. Similar: \$23.00 (\$46.00 regular price) https://www.polishpotteryshop.com/products/glass-24-glass-flower-lava-red	Est: 0.00 C/S: 39.99 Fee: 0.00
SI No: 18 Inv#: 24 Wt: 0 Ctn Avail: No	 Image1  Image2	Libson Gard Rock Shot Glass	Broken into pieces in transit. Retail: \$23.49 https://www.amazon.com/Hard-Rock-Cafe-HRC-Lisbon/dp/B07SBR7K8S	Est: 0.00 C/S: 23.49 Fee: 0.00
SI No: 19 Inv#: NA Wt: 0 Ctn Avail: No		Fire Stick Charging Cord	Missing. Retail: \$8.85 https://www.amazon.com/Streaming-Express-Premier-Charging-Replacement/dp/B0814SKLN1/ref=sr_1_3	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 20		Laptop Bag	Found. No claim.	Est: 0.00









Inv#: NA			C/S: 0.00
Wt: 0			Fee: 0.00
Ctn Avail: No			
SI No: 21	Cords in Laptop Bag	Found. No claim.	Est: 0.00
Inv#: NA			C/S: 0.00
Wt: 0			Fee: 0.00
Ctn Avail: No			
SI No: 22	Metal Basket Laundry	Missing	Est: 0.00
Inv#: NA			C/S: 0.00
Wt: 0			Fee: 0.00
Ctn Avail: No			
SI No: 23	Dryer Balls	Missing	Est: 0.00
Inv#: NA			C/S: 0.00
Wt: 0			Fee: 0.00
Ctn Avail: No			
SI No: 24	Mounted Metal Mat Mount	Found. No claim.	Est: 0.00
Inv#: NA			C/S: 0.00
Wt: 0			Fee: 0.00
Ctn Avail: No			
SI No: 25	   	Laundry Hamper	Est: 0.00 C/S: 26.00 Fee: 0.00 Metal frame bent, netting torn, transit related. Similar: \$26.00 https://www.crateandbarrel.com/canvas-light-natural-hamper/s566727
Inv#: NA			
Wt: 0			
Ctn Avail: No			
SI No: 26	   	Air Compressor	Est: 0.00 C/S: 0.00 Fee: 0.00 Carburetor on top back right is bent. Gauge cracked. Item noted as DBO at origin, we cannot say this is transit related, and the item shows a good bit of wear and age. This damage doesn't appear to be fresh. Retails: \$159.99 https://www.searshometownsto
Inv#: NA			
Wt: 0			
Ctn Avail: No			

Image4

res.com/product/Craftsman-3-GAL-3-Gallon-Air-Compressor-with-Hose-and-Accessory-Kit

SI No: 27

Inv#: NA

Wt: 0

Ctn Avail:

No



Image1



Image2

Treadmill

Missing end cap. This was not listed as PED, no it could be new transit damage. The parts for this model are no longer available. An appearance allowance may be appropriate since this is cosmetic only.

Est: 0.00

C/S: 0.00

Fee: 0.00

Retails: \$359.99

<https://www.amazon.com/XTER-RA-Fitness-TR150-Folding-Treadmill/dp/B01M0L0D90>



Image3



Image4

Inspection/Final Report

Date of Report	:		Date Completed	:	
Type of Report	:	Inspection/Final Report	Expenses	:	\$ 0.00
Inspection Fee	:	\$ 250.00	Tax	:	\$ 0.00
Total C/S	:	\$ 740.09	Total Est	:	\$ 125.00
Fees	:	\$ 0.00	Total	:	\$ 250.00
Additional information	:				