

Inspection/Final Report

Client	: Suddath Relocation Systems	Adjuster	: SGS Claims
Adjuster Ph	:	Date	: Jun 12, 2023
Received		Estatus Ref #	: 672377
Claim #	: 1431054	Admin	: Jeff Schatzman
Valuations	: FVP	Additional Information	:
Shipper	: JORGE DELGADO	Cell Ph	: 310-351-0619
Home Ph	: 310-351-0619	E-Mail	: JADUSA14@GMAIL.COM
Work Ph	: 310-351-0619		
Address	: 117 13TH ST, BLACK EAGLE MT 59414		

Items List

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 1 Inv#: 83 Wt: 0 Ctn Avail: No	     	sofa living room	<p>The frame of the sofa is broken all the way through. This appears to be new transit damage, a local repair firm could repair this to industry standards, our charge for this repair would be \$275.00</p> <p>Similar: \$1,370.87 for the sofa and loveseat</p> <p>https://www.overstock.com/Home-Garden/Craigmont-2-Piece-Standard-Living-Room-Set/35585394/product.html?opre=1&option=68403510</p>	Est: 0.00 C/S: 0.00 Fee: 0.00



Image7



Image8

SI No: 2**Inv#:** 84**Wt:** 0**Ctn Avail:**

No



Image1



Image2



Image3



Image4



Image5



Image6



Image7

loveseat living room

The frame on the loveseat is broken all the through. This appears to be new transit damage, this is repairable, a local repair firm can repair the frame to industry standards. Our charge for this repair would by \$275.00

Similar: \$1,370.87 for the sofa and loveseat

<https://www.overstock.com/Home-Garden/Craigmont-2-Piece-Standard-Living-Room-Set/35585394/product.html>

Est: 0.00**C/S:** 0.00**Fee:** 0.00**SI No:** 3**Inv#:** 85**Wt:** 0**Ctn Avail:**

No



Image1



Image2

coffee table

The white coffee table has small dents on the table slats. This appears to be new transit damage, but this is compressed wood, not repairable.

Similar: \$179.99

<https://www.wayfair.com/furniture/pdp/breakwater-bay-wrenshall-4-legs-coffee-table-with-storage-w000297227.html>

Est: 0.00**C/S:** 0.00**Fee:** 0.00



Image3



Image4

SI No: 4**Inv#:** 86**Wt:** 0**Ctn Avail:**

No



Image1



Image2

bookcase

There are small chips and dings on the shelves side supports of the matching book cases. This appears to be new transit damage, not repairable for less than the value of the item.

Similar: \$129.99/Repair estimate: \$175.00

<https://tribesigns.com/products/1-tribesigns-5-tier-bookshelf-62-99-storage-shelf-with-x-back-frame>




Image3



Image4



Image5

SI No: 5**Inv#:** 88**Wt:** 0**Ctn Avail:**

No




Image1



Image2

end tables

The white matching white end tables have minor dings throughout the tops, edges and legs. This appears to be new transit damage, not repairable for less than the value of the items.

Similar: \$75.98 each/Repair estimate: \$125 each

<https://www.wayfair.com/furniture/pdp/breakwater-bay-wrenshall-end-table-with-storage-w004630067.html>



Image3



Image4

Est: 0.00**C/S:** 0.00**Fee:** 0.00**Est:** 0.00**C/S:** 0.00**Fee:** 0.00



Image5



Image6

SI No: 6**Inv#:** 89**Wt:** 0**Ctn Avail:**

No



Image1



Image2

white lamps (there are two identical lamps)

The two identical white lamps have dents on the base and are leaning sideways. This appears to be new transit damage.

Similar: \$69.35 each

<https://www.lowes.com/pd/Globe-Electric-Dixon-65-in-Matte-White-Torchiere-Floor-Lamp/5013382277>

Est: 0.00**C/S:** 0.00**Fee:** 0.00

Image3



Image4



Image5

SI No: 7**Inv#:** 90**Wt:** 0**Ctn Avail:**

No



Image1



Image2

bookcase

There are small chips and dings on the shelves side supports of the matching book cases. This appears to be new transit damage, not repairable for less than claimed amount.

Similar: \$129.99/Repair estimate: \$150.00

<https://tribesigns.com/products/1-tribesigns-5-tier-bookshelf-62-99-storage-shelf-with-x-back-frame>

Est: 0.00**C/S:** 0.00**Fee:** 0.00

Image3

SI No: 8**Inv#:** 91

TV Stand

The white TV stand rsf panel has a black scuff mark near the top and a dent near the front

Est: 0.00**C/S:** 0.00

Wt: 0
Ctn Avail:
No




Image1 Image2



Image3

edge. This appears to be new transit damage, not repairable, this is compressed wood.
Similar: \$298.50
<https://www.wayfair.com/furniture/pdp/hashtag-home-allegra-tv-stand-for-tvs-up-to-50-w005933018.html>

Fee: 0.00

SI No: 9
Inv#: 98
Wt: 0
Ctn Avail:
No




Image1 Image2



Image3 Image4



Image5

trash can

The lid and the back of the stainless-steel trashcan are both dented. There was no damage noted at origin for this item, this appears to be new transit damage.
Similar: \$44.99
https://www.amazon.com/Finger-Print-Stainless-Kitchen-Garbage-Removable/dp/B09L7XFQTV/ref=asc_df_B09L7XFQTV/

Est: 0.00

C/S: 0.00

Fee: 0.00

SI No: 10
Inv#: 99
Wt: 0
Ctn Avail:
No

Duplicate entry.

Est: 0.00

C/S: 0.00

Fee: 0.00

SI No: 11
Inv#: 126
Wt: 0
Ctn Avail:

bed slats

The wooden bed slats are broken in half from transit.
Similar replacement slats: \$55.95
<https://www.homedepot.com/p/>

Est: 0.00

C/S: 0.00

Fee: 0.00

No



Image1



Image2

1-in-x-4-in-x-5-ft-Pine-Queen-Bed-Slat-Board-7-Pack-231575/207182035



Image3



Image4



Image5



Image6



Image7

SI No: 12



Image1



Image2

Inv#: 127

bed side

Wt: 0

The bed side rail has a portion of the bottom lip that supports the slats is broken off. This appears to be new transit damage, not repairable to industry standards.

Est: 0.00

Ctn Avail:

Similar side rail: \$230.99
https://www.amazon.com/Bed-Claw-Heavy-Duty-Replacement-Medium/dp/B07NPYB1VG/ref=asc_df_B07NPYB1VG/

No

C/S: 0.00

Fee: 0.00



Image3



Image4



Image5



Image6




Image7

SI No: 13**Inv#:** 124**Wt:** 0**Ctn Avail:**

No



Image1



Image2

end table

The end table/nightstand top and bottom shelf are both torn off and the top shelf is bent on the corners. This appears to be new transit damage, it is not repairable, this is compressed wood.

Similar: \$64.99

https://www.amazon.com/Sauder-420274-North-Avenue-table/dp/B01K6PLVGA/ref=asc_df_B01K6PLVGA/



Image3



Image4

Est: 0.00**C/S:** 0.00**Fee:** 0.00**SI No:** 14**Inv#:** 136**Wt:** 0**Ctn Avail:**

No



Image1



Image2

bathroom rack

The metal bathroom rack has multiple pieces warped and bent from transit.

Similar: \$49.00

<https://www.amazon.com/Zenna-Home-2265NN-Bathroom-Nickel/dp/B01M7Y4ZLZ>



Image3



Image4

Est: 0.00**C/S:** 0.00**Fee:** 0.00



Image5

SI No: 15			2 rods	The curtain rods are badly warped into a deep curve from transit.	Est: 0.00
Inv#: 221					C/S: 0.00
Wt: 0					Fee: 0.00
Ctn Avail:					
No					
	Image1	Image2			
	Image3	Image4			

SI No: 16			fan floor	The base of the standing fan is shattered, this appears to be from transit. Similar retails: \$44.99 https://www.target.com/p/lasko-18-34-stand-oscillating-fan-black-/A-81411292#lnk=sametab	Est: 0.00
Inv#: 231					C/S: 0.00
Wt: 0					Fee: 0.00
Ctn Avail:					
No					
	Image1	Image2			
	Image3				

SI No: 17			bedding	The Threshold bedding has holes throughout the fabric. This appears to be new transit damage. Similar: \$99.00 https://www.target.com/p/space-dyed-cotton-linen-comforter-sham-set-threshold-/A-82022312	Est: 0.00
Inv#: 146					C/S: 0.00
Wt: 0					Fee: 0.00
Ctn Avail:					
No					
	Image1	Image2			




Image3

Inspection/Final Report

Date of Report	:	Jun 12, 2023	Date Completed	:
Type of Report	:	Inspection/Final Report	Expenses	:
Inspection Fee	:	\$ 150.00	Tax	:
Total C/S	:	\$ 0.00	Total Est	:
Fees	:	\$ 0.00	Total	:
Additional information	:	virtual inspection		\$ 150.00