










Inspection/Final Report

Client	: Total Military Management	Adjuster	: TMM Inspections
Adjuster Ph	:	Date	: Feb 23, 2023
GBL#	: BGAC0613399	Received	
Valuations	: FVP	Estatus Ref #	: 667384
Shipper	: Cheryl Spivey-Johnston	Admin	: Jeff Schatzman
Home Ph	:	Additional Information	:
Work Ph	:	Cell Ph	:
Address	: San Antonio TX	E-Mail	:

Items List

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 1 Inv#: 73 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3	Dell Monitor	The monitor will not power on. There is no external damage to the unit to indicate any transit damage. A 3rd party computer service would need to assess this item to determine the cause and reparability. Retails: \$1,449.99/Claimed: \$1,400.00 https://www.dell.com/en-us/shop/dell-ultrasharp-38-curved-usb-c-hub-monitor-u3821dw/apd/210-ayle/monitors-monitor-accessories	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 2 Inv#: 140 Wt: 0 Ctn Avail: No		Table with Glass Top	Shipper would like to disregard this item.	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 3 Inv#: 173 Wt: 0 Ctn Avail: No	 Image1	Office Swivel Chair	Shipper discarded.	Est: 0.00 C/S: 0.00 Fee: 0.00
		Wide Format Plotter	The HP 8AG32A stands on the	Est:

SI No: 4 Inv#: 176 and 177 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3		<p>bottom of the base are broken off from transit, so the papers fall directly to the floor. The plotter appears to be in good working order. A 3rd party should be able to order this damaged part and install it. Retails: \$699.00/Claimed: \$700.00/Repair estimate: \$250 parts and labor https://www.hp.com/us-en/shop/pdp/hp-designjet-t210-24-in-printer</p>	250.00 C/S: 0.00 Fee: 0.00
SI No: 5 Inv#: 178,179,180 Wt: 0 Ctn Avail: No	 Image1	Printer Stand with Glass Doors	The rsf glass door is broken off and missing from the printer stand. Transit damage, not repairable. Similar: \$157.49/Claimed: \$250.00 https://www.sears.com/tkm-home-rolling-printer-stand-mobile-cabinet-cart/p-A114378692	Est: 0.00 C/S: 157.49 Fee: 0.00
SI No: 6 Inv#: ADD ON Wt: 0 Ctn Avail: No	 Image1	Dyson vacuum	The filter on the Dyson vacuum was missing. The shipper replaced the filter. Replacement filter: \$29.99 https://www.dyson.com/support/journey/replacement-parts/969082-01	Est: 0.00 C/S: 0.00 Fee: 0.00

Inspection/Final Report

Date of Report	:		Date Completed	:	
Type of Report	:	Inspection/Final Report	Expenses	:	\$ 0.00
Inspection Fee	:	\$ 250.00	Tax	:	\$ 0.00
Total C/S	:	\$ 157.49	Total Est	:	\$ 250.00
Fees	:	\$ 0.00	Total	:	\$ 250.00
Additional information	:				