






























Repair/Final Report

Client	: Tier One Relocations LLC	Adjuster	: Inspection Tier One
Adjuster Ph	:	Date	: Mar 02, 2023
GBL#	: BGAC0610077	Received	
Valuations	: Other	Estatus Ref #	: 667729
Shipper	: Joel Crespo	Admin	: Jeff Schatzman
Home Ph	:	Additional Information	:
Work Ph	:	Cell Ph	:
Address	: Fort Benning GA	E-Mail	:

Items List

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 1 Inv#: 106 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3  Image4  Image5  Image6	Bicycle	The handle bar is broken off of the child's bike frame. This is fresh damage and is not repairable for less than claimed amount. Retails: \$65.47/ Claimed \$58.00/Repair estimate: \$125.00 https://www.walmart.com/ip/16-Boy-s-Flex-Bicycle/46712779	Est: 0.00 C/S: 58.00 Fee: 0.00
SI No: 2 Inv#: 107 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3  Image4	Bicycle	The orange child's bike handle bar is twisted. This is fresh damage, not repairable for less than claimed. Similar: \$118.96/ Claimed \$73.00/Repair estimate: \$125.00	Est: 0.00 C/S: 73.00 Fee: 0.00
SI No: 3		Bicycle	The Nishiki adult bike handle bar is bent and the pedal gears	Est: 0.00

<div>Inv#: 108</div> <div>Wt: 0</div> <div>Ctn Avail: No</div>	<div><div></div><div></div><div></div><div></div><div></div><div></div></div>		<p>click. A local bike repair service would need to assess this bike to determine cause of the clicking gears, there is no visible damage that we can see, and the handle bar issue needs to be assessed for repair as well, this is fresh damage. The shipper will need to transport the bike to and from the inspection with a local 3rd party if the inspection is authorized. The cost of this will exceed the settlement amount requested.</p> <p>Retails: \$330.00/Claimed: \$100.00/Repair estimate: \$200.00</p> <p>https://www.dealnews.com/products/Nishiki/Nishiki-Mens-Pueblo-26-Mountain-Bike/75088.html</p>	<div>C/S: 100.00</div> <div>Fee: 0.00</div>
<div>SI No: 4</div> <div>Inv#: 109</div> <div>Wt: 0</div> <div>Ctn Avail: No</div>	<div><div></div><div></div><div></div><div></div><div></div></div>	Bicycle	<p>The black Side Winder bicycle handles are slightly bent and the pedal/gear is slipping/clicking. A local bike repair service would need to assess this bike to determine cause of the clicking/slipping gears, there is no visible damage that we can see, and the handle bar issue needs to be assessed for repair as well, this is fresh damage. The shipper will need to transport the bike to and from the inspection with a local 3rd party if the inspection is authorized. The cost of this will exceed the settlement amount requested.</p> <p>Similar: \$248.00/Claimed: \$150.00/Repair estimate: \$200.00</p> <p>https://www.walmart.com/ip/Schwinn-Sidewinder-Mountain-Bike-26-inch-Wheels-21-Speeds-Mens-Style-Black/651876804</p>	<div>Est: 0.00</div> <div>C/S: 150.00</div> <div>Fee: 0.00</div>
<div>SI No: 5</div> <div>Inv#: 194</div> <div>Wt: 0</div>		Living Room TV Stand /Ashley	<p>The casing for the TV stand has completely fallen apart and separated at the joints. The legs are broken off. This is fresh</p>	<div>Est: 0.00</div> <div>C/S: 599.00</div> <div>Fee: 0.00</div>

Ctn Avail: No	 Image1	 Image2		damage but is not repairable, item is constructed of pressed wood. Retails: \$599.00 (Discontinued)/Claimed: \$700.00 https://www.ashleyfurniture.com/p/esmarina_62_tv_stand/W815-48.html	
SI No: 6 Inv#: 214 Wt: 0 Ctn Avail: No	 Image1	 Image2	Headboard	The King-size bed rear bottom support is pulled from the joints. This is fresh damage, we can repair it. Similar: \$625.24/Claimed: \$1,200.00/Repair estimate: \$150.00 https://www.valuecitynj.com/item/ryleigh-king-bed/1676158801	Est: 150.00 C/S: 0.00 Fee: 0.00
SI No: 7 Inv#: 222 Wt: 0 Ctn Avail: No	 Image1	 Image2	Wall Mirror	The full length mirror is cracked. This is fresh damage. Tag on back notes the price at \$19.99/Claimed: \$35.00	Est: 0.00 C/S: 19.99 Fee: 0.00
SI No: 8 Inv#: 146 Wt: 0 Ctn Avail: No			Dolly (red)	Missing	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 9 Inv#: 200 Wt: 0 Ctn Avail: No	 Image1	 Image2	Sectional /H. M. Richards	The grey sectional sofa raf front kick panel is torn and the Isf isb of the corner wedge has a tear. This is fresh damage but is not repairable. Similar: \$4,409.95/Claimed: \$2,000.00 https://www.raymourflanigan.com/living-rooms/sectional-sofas/braelyn-3-pc-microfiber-sectional-sofa-299295557	Est: 0.00 C/S: 2,000.00 Fee: 0.00

Repair/Final Report

Date of Report	: Mar 07, 2023	Date Completed	:
Type of Report	: Repair/Final Report	Expenses	: \$ 0.00
Inspection Fee	: \$ 250.00	Tax	: \$ 0.00
Total C/S	: \$ 2,999.99	Total Est	: \$ 150.00
Fees	: \$ 0.00	Total	: \$ 250.00
Additional information	:		