








Inspection/Final Report

Client	: SIRVA International	Adjuster	: No Email SIRVA
Adjuster Ph	:	Date	: Sep 01, 2023
Claim #	: 12884-3	Received	
Valuations	: Other	Estatus Ref #	: 677641
Shipper	: Laurie Radmer	Admin	: Jeff Schatzman
Home Ph	:	Additional Information	:
Work Ph	:	Cell Ph	:
Address	: NA	E-Mail	:

Items List

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
Sign				
SI No: 1 Inv#: Wt: 0 Ctn Avail: No	 Image1  Image2  Image3  Image4	Secretary Cabinet (Top)	The wooden secretary cabinet (top) RSF edge was cracked during the move and the side was detached from the bottom section. Tech repaired the damage by securing the top to the bottom of the secretary cabinet.	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 2 Inv#: Wt: 0 Ctn Avail: No	 Image1  Image2  Image3	Remote Control	The Vizio TV remote control was lost during the move. Replacement: \$6.44 https://www.amazon.com/XRT135-Remote-Control-M55-E0-E50x-E1/dp/B07GJJ9FYF^	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 3		Secretary Furniture (Bottom) cherry	The cherry secretary bottom RSF had a large chunk of the	Est: 0.00

Inv#:
Wt: 0
Ctn Avail:
No



Image1



Image2

wood

side pulled off during the move.
Tech repaired the side and
refinished the damaged area.

C/S: 0.00

Fee: 0.00



Image3



SI No: 4
Inv#:
Wt: 0
Ctn Avail:
No



Image1



Image2

Tray - Music Stand

The music stand lost an
adjustable wood peg during
move.
Tech replaced peg with a
decorative brass peg.

Est: 0.00

C/S: 0.00

Fee: 0.00



Image3



Image4



SI No: 5
Inv#:
Wt: 0
Ctn Avail:
No



Image1



Image2

Upholstered recliner

The recliner base frame was
damaged and separated during
the move. Tech glued it back
together. Repaired.

Est: 0.00

C/S: 0.00

Fee: 0.00



Image3




Image4



Image5



Image6



Image7



Image8



SI No: 6

Lead Crystal

One small Lead crystal

Est: 0.00

Inv#: ADD
ON
Wt: 0
Ctn Avail:
No




Image1



Image2




Image3

candlestick holder
set

candlestick holder was lost
during the move.

Similar: \$119.98

<https://www.amazon.com/Marquis-Treviso-Collection-Candle-Sticks/dp/B00029OPVY?>

C/S: 0.00

Fee: 0.00

SI No: 7
Inv#: ADD
ON
Wt: 0
Ctn Avail:
No



Image1



Image2

Crystal Tray for
Cream & Sugar
Bowls

The crystal tray for the cream
and sugar bowls is missing.

Est: 0.00

C/S: 0.00

Fee: 0.00

Signature

The signature below is for customer acceptance of all repairs that are designated by "Accepted" on each repaired item.

Inspection/Final Report

Date of Report	:		Date Completed	:	
Type of Report	:	Inspection/Final Report	Expenses	:	\$ 0.00
Inspection Fee	:	\$ 0.00	Tax	:	\$ 0.00
Total C/S	:	\$ 0.00	Total Est	:	\$ 0.00
Fees	:	\$ 0.00	Total	:	\$ 0.00
Additional information	:				