






Repair/Final Report

Client	: Unigroup / Mayflower /United	Adjuster	: Team 4 Claims
Adjuster Ph	: 855-252-8913	Date	: Jul 06, 2023
Claim #	: U0103-17672-3	Received	
Valuations	: FVP	Estatus Ref #	: 673522
Shipper	: Jerry Collier	Admin	: Andrew Maliszewski
Home Ph	:	Additional Information	:
Work Ph	:	Cell Ph	: 281-898-2813
Address	: 2884 Cravey Dr NE Atlanta, GA 30345	E-Mail	: jerrycollier@gmail.com

Items List

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 1 Inv#: 15 Wt: 2 Ctn Avail: No	 Image1  Image2	Plastic Organizer	Front cracked Appears to be fresh moving damage Not repairable. \$50 claim higher than \$21.98 similar replacements available on Amazon. Liability at your discretion.	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 2 Inv#: 58 Wt: 1 Ctn Avail: No	 Image1  Image2  Image3	Plastic Tub	Top front broken Appears to be fresh moving damage Not repairable. \$38 claim more than \$15.21 Amazon replacement (see link below) https://www.amazon.com/Sterilite-20518006-Stackable-Storage-Drawer/dp/B001MY0NGE/ref=sr_1_7?crd=3AS40CQPWQIBT&keywords=plastic+storage+drawer&qid=1689727523&s=home-	Est: 0.00 C/S: 0.00 Fee: 0.00

SI No: 3

Inv#: 89

Wt: 50

Ctn Avail:
No



Image1



Image2

Shelf

Multiple scratches and dents in the wood and on the metal frame.

Est: 490.00

C/S: 0.00

Fee: 0.00

Appears to be fresh moving damage due to poor packaging and handling

Repairable in shop for \$490, less than \$700 claim or estimated \$700 replacement.




Image3



Image4



Image5



Image6



Image7




Image8




Image9



Image10



Image11

SI No: 4

Inv#: 90

Wt: 80

Ctn Avail:
No




Image1




Image2

Desk

Three white paint marks on the back of the desk

Est: 0.00

C/S: 0.00

Fee: 275.00

Appears to be fresh moving damage due to poor packaging

\$275 repair, less than \$1100 claimed or estimated \$1100 replacement.

Technician repaired on site




Image3

SI No: 5

Inv#: 51

Wt: 1

Ctn Avail:
















Glass

Customer T/A
\$6 claimed

Est: 0.00

C/S: 0.00

Fee: 0.00

No				
SI No: 6 Inv#: 124 Wt: 100 Ctn Avail: No	 Image1  Image2  Image3  Image4  Image5  Image6  Image7  Image8	Couch	<p>Pretty much every corner on the sofa has black grease stains with the fabric rubbed in certain areas</p> <p>Appears to be fresh moving damage due to poor packaging and handling</p> <p>Likely cleanable for under \$775 less than \$5000 claimed.</p> <p>Repair requires on site cleaning \$240 specialist evaluation, deductible from full cleaning, if successful.</p>	Est: 775.00 C/S: 0.00 Fee: 0.00
SI No: 7 Inv#: 58 Wt: 15 Ctn Avail: No	 Image1  Image2  Image3  Image4  Image5  Image6  Image7	KitchenAid Mixer	<p>A couple fresh nicks in the paint on top</p> <p>Appears to be fresh moving damage due to poor packaging and handling</p> <p>Not repairable. \$400 claim similar to replacement. Item still fully operational. Suggest allowance.</p>	Est: 0.00 C/S: 0.00 Fee: 0.00
SI No: 8 Inv#: 147 Wt: 1 Ctn Avail: No		Fishing Pole	<p>Pole broken at the tip</p> <p>Appears to be fresh moving damage due to poor packaging</p> <p>Not repairable. \$75 claim similar to replacement. Suggest cash out.</p>	Est: 0.00 C/S: 75.00 Fee: 0.00

Repair/Final Report

Date of Report	: Jul 18, 2023	Date Completed	: Jul 11, 2023
-----------------------	----------------	-----------------------	----------------

Type of Report : Repair/Final Report
Inspection Fee : \$ 0.00
Total C/S : \$ 75.00
Fees : \$ 275.00
Additional information :

Expenses : \$ 0.00
Tax : \$ 0.00
Total Est : \$ 1,265.00
Total : \$ 275.00