

Inspection/Final Report

Client	: Total Military Management	Adjuster	: TMM Inspections
Adjuster Ph	:	Date	: Feb 20, 2023
GBL#	: HAF0647578	Received	
Valuations	: FVP	Estatus Ref #	: 667189
Shipper	: Laurence Peterson	Admin	: Jeff Schatzman
Home Ph	:	Additional Information	:
Work Ph	:	Cell Ph	:
Address	: Colorado Springs CO	E-Mail	:

Items List










#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
SI No: 1 Inv#: 414671 7-085 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3  Image4  Image5	TV Stand	The TV stand has both back legs broken off with the rsf leg completely missing. New transit damage, not repairable. Similar: \$235.99/Claimed: \$353.59 https://www.amazon.com/Crosley-Furniture-Alexandria-42-inch-Stand/dp/B00495KM2S/ref=asc_df_B00495KM2S/	Est: 0.00 C/S: 235.99 Fee: 0.00
SI No: 2 Inv#: 414671 7-078 Wt: 0 Ctn Avail: No	 Image1  Image2  Image3  Image4	3 Shelf Cubicle	The 3-shelf cube bottom shelf is ripped out near the dowels. New transit damage, not repairable MDF. Similar: \$23.99/Claimed: \$35.00 https://www.target.com/p/iris-usa-3-cube-modular-storage-box-shelf-brown-oak/-/A-88504978	Est: 0.00 C/S: 23.99 Fee: 0.00



Image5

SI No: 3

Inv#:
414671
7-047

Wt: 0

Ctn Avail:
No



Image1



Image2



Image3



Image4



Image5

Standing Jewelry Box

Both of the rsf legs as well as the rsf side bottom trim broke off in transit. Repairable, but cost will exceed settlement amount requested.

Similar: \$119.99/Claimed: \$99.99/Repair estimate: \$125.00

<https://www.target.com/p/maev-e-jewelry-armoire-espresso-linon/-/A-86041880>

Est: 0.00

C/S: 99.99

Fee: 0.00

SI No: 4

Inv#:
414671
7-091

Wt: 0

Ctn Avail:
No

PC Gaming Desk

Moving company took the desk away. No photos

Est: 0.00

C/S: 0.00

Fee: 0.00

SI No: 5

Inv#:
414671
7-005

Wt: 0

Ctn Avail:
No




Image1




Image2




Image3




Image4

2 Drawer Nightstand

Shipper claimed the nightstand was wobbly but technician found it to be stable, no issues. Retails: \$179.99/Claimed: \$169.99

<https://www.cymax.com/Glory-Furniture-Louis-Phillipe-2-Drawer-Nightstand-in-Cappuccino-G3125-N.htm>

Est: 0.00

C/S: 0.00

Fee: 0.00

SI No: 6

Inv#:
414671
7-095

Wt: 0

Ctn Avail:
No




Image1



Image2



Image3




Image4

3 Drawer Dresser

The 3-drawer dresser is missing the top rsf wooden drawer glide that attaches to case. This was noted PED at origin, broken drawer.








Similar: \$199.00 /Claimed: \$121.47



<https://davincibaby.com/products/kalani-3-drawer-dresser>

Est: 0.00







C/S: 0.00

Fee: 0.00

	Image3	Image4			
SI No: 7 Inv#: 414671 7-096 Wt: 0 Ctn Avail: No	 Image1	 Image2	6 Drawer Dresser The 6-drawer dresser rsf side is separating from the case. Additionally it is missing toe kick. New transit damage, not repairable. Similar: \$499.95/Claimed: \$239.98 https://www.shopbedmart.com/product/furniture/bedroom/mayville-dresser/	Est: 0.00 C/S: 239.98 Fee: 0.00	
SI No: 8 Inv#: 414671 7-115 Wt: 0 Ctn Avail: No	 Image1	 Image2	Pink Vanity The pink vanity is missing hardware to assemble, lost in transit. Not repairable for less than value of the item. Similar: \$129.00/Claimed: \$207.00/Repair estimate: \$225.00 https://www.walmart.com/ip/Roundhill-Furniture-Moniya-Wood-Vanity-Table-and-Stool-Set-Pink/56204365	Est: 0.00 C/S: 129.00 Fee: 0.00	
SI No: 9 Inv#: 414671 7-084 Wt: 0 Ctn Avail: No			Black Book Shelf Shipper discarded.	Est: 0.00 C/S: 0.00 Fee: 0.00	
SI No: 10 Inv#: Unknown Wt: 0 Ctn Avail: No	 Image1	 Image2	Red 3 Seat Couch The red sofa is missing 2 feet and has 1 foot broken. This is new transit damage, we can order replacement feet and install. Similar: \$769.99/Claimed: \$399.99/Repair estimate: parts and labor: \$300.00 https://www.wayfair.com/furniture/pdp/wade-logan-bayswater-845-rolled-arm-sofa-w004180318.html?piid=328817544	Est: 300.00 C/S: 0.00 Fee: 0.00	
SI No: 11 Inv#: 414671 7-054 Wt: 0 Ctn Avail:	 Image1	 Image2	King Bed Footboard Rail The wooden footboard rail is split all the way through. Repairable, new transit damage. Similar: \$239.00/Claimed: \$271.15/Repair estimate:	Est: 250.00 C/S: 0.00 Fee: 0.00	

No			\$250.00 https://www.amazon.com/Zinus-Deluxe-Platform-Boxspring-Support/dp/B01MRH37QD
	Image3	Image4	

SI No: 12	Bathroom 3 Shelf Towel Rack	Missing.	Est: 0.00
Inv#: 414671 7-060			C/S: 0.00 Fee: 0.00
Wt: 0			
Ctn Avail: No			

SI No: 13			Computer Chair	The rolling office chair is missing a wheel, lost in transit. Not repairable. Similar: \$91.29/Claimed \$68.99 https://www.amazon.com/AmazonBasics-Puresoft-PU-Padded-Mid-Back-Computer/dp/B081H3Y5NW/ref=sr_1_4	Est: 0.00 C/S: 68.99 Fee: 0.00
Inv#: 414671 7-080	Image1	Image2			
Wt: 0					
Ctn Avail: No					
	Image3				
					
	Image5				

Inspection/Final Report

Date of Report	:		Date Completed	:	
Type of Report	:	Inspection/Final Report	Expenses	:	\$ 0.00
Inspection Fee	:	\$ 250.00	Tax	:	\$ 0.00
Total C/S	:	\$ 797.94	Total Est	:	\$ 550.00
Fees	:	\$ 0.00	Total	:	\$ 250.00
Additional information	:				