







**Inspection/Final Report**

<b>Client</b> :	Eagle Claims Services	<b>Adjuster</b> :	Sarah Littlefield
<b>Adjuster Ph</b> :		<b>Date</b> :	Mar 01, 2023
<b>Claim #</b> :	55-0067-23	<b>Received</b>	
<b>Valuations</b> :	FVP	<b>Estatus Ref #</b> :	667683
<b>Shipper</b> :	<b>George VanBuren</b>	<b>Admin</b> :	Jeff Schatzman
<b>Home Ph</b> :		<b>Additional Information</b>	
<b>Work Ph</b> :		<b>Cell Ph</b> :	
<b>Address</b> :	San Antonio TX	<b>E-Mail</b> :	

**Items List**

#	Photos	Item Description	Condition/ Recommendations/ Repairs	Costs
<b>SI No:</b> 1 <b>Inv#:</b> 296 <b>Wt:</b> 0 <b>Ctn Avail:</b> No	 Image1  Image2	LED 3D Smart TV	The Samsung UN55F7100AF TV rsf portion of the screen is cracked from transit. This model is discontinued. Retail: \$1,699.99/Claimed: \$1,449.00 <a href="https://www.bestbuy.com/site/questions/samsung-55-class-54-5-8-diag--led-1080p-240hz-smart-3d-hdtv/8224045">https://www.bestbuy.com/site/questions/samsung-55-class-54-5-8-diag--led-1080p-240hz-smart-3d-hdtv/8224045</a>	<b>Est:</b> 0.00 <b>C/S:</b> 1,449.00 <b>Fee:</b> 0.00
<b>SI No:</b> 2 <b>Inv#:</b> 331 <b>Wt:</b> 0 <b>Ctn Avail:</b> No	 Image1  Image2	TV Stand	The TV stand arrived with only 3 bolts to reassemble. There are 9 missing, these are specific to the tv stand and we can't replace them. Not repairable transit damage. Retails: \$219.99/Claimed: \$300.00 <a href="https://www.wayfair.com/furniture/pdp/orren-ellis-tv-stand-for-tvs-up-to-50-w001911862.html">https://www.wayfair.com/furniture/pdp/orren-ellis-tv-stand-for-tvs-up-to-50-w001911862.html</a>	<b>Est:</b> 0.00 <b>C/S:</b> 219.99 <b>Fee:</b> 0.00
<b>SI No:</b> 3 <b>Inv#:</b> 257 <b>Wt:</b> 0 <b>Ctn Avail:</b> No	 Image1  Image2	Cabinet	The white bathroom cabinet arrived with broken legs from transit. Not repairable pressed wood. Similar: \$105.99/Claimed: \$119.00	<b>Est:</b> 0.00 <b>C/S:</b> 105.99 <b>Fee:</b> 0.00

[https://www.amazon.com/Spirich-Bathroom-Toilet-SpaceSaver-Organizer/dp/B07S1VBXM4/ref=asc\\_df\\_B07S1VBXM4/](https://www.amazon.com/Spirich-Bathroom-Toilet-SpaceSaver-Organizer/dp/B07S1VBXM4/ref=asc_df_B07S1VBXM4/)

**SI No:** 5  
**Inv#:** 116  
**Wt:** 0  
**Ctn Avail:**  
No



Image1



Image2

Wine Fridge

The Magic Chef wine fridge will not cool and is showing an error code EEF which according to the manual for this item means there is an issue with the compressor or a freon leak. This is a wear related issue and not transit related damage in our opinion, and there is no visible damage to the item to indicate it was damage in transit to cause this error to occur.

**Est:** 0.00  
**C/S:** 0.00  
**Fee:** 0.00

Retails \$491.68 /Claimed:  
\$600.00

<https://www.homedepot.com/p/Magic-Chef-Beverage-23-4-in-154-12-oz-Can-Beverage-Cooler-Stainless-Steel-HMBC58ST/300509606>



Image3



Image4

**SI No:** 6  
**Inv#:** ADD  
ON  
**Wt:** 0  
**Ctn Avail:**  
No



Image1




Image2

Lamp

The base of the lamp is chipped on the corner from transit. Similar: \$97.99  
<https://www.michaels.com/product/garden-lattice-table-lamp-in-light-blue-D0547485>

**Est:** 0.00  
**C/S:** 97.99  
**Fee:** 0.00

**SI No:** 7  
**Inv#:** 300  
**Wt:** 0  
**Ctn Avail:**  
No



Image1




Image2

7 Drawer Dresser

The dresser has back panel is cracked and the drawer guides are broken on the bottom left drawer. Repairable, new transit damage.

**Est:** 300.00  
**C/S:** 0.00  
**Fee:** 0.00

Similar: \$799.99/Claimed:  
\$1,080.00/Repair estimate:  
\$300.00 parts and labor  
<https://www.homedepot.com/ep/Brinley-7-Drawer-Cherry-Dresser-CN600DR/304580728>




Image3

**SI No:** 8  
**Inv#:** ADD  
ON  
**Wt:** 0  
**Ctn Avail:**  
No



Image1

Picture frame

The wooden frame glass panel is shattered from transit. Similar: \$22.99  
<https://thedisplayguys.com/products/11-x-14-natural-oak-wood-shadow-box-frame>

**Est:** 0.00  
**C/S:** 22.99  
**Fee:** 0.00

**SI No:** 9  
**Inv#:** ADD

Tea Pitcher

The glass pitcher is cracked all the way through from transit.

**Est:** 0.00

ON

Wt: 0

Ctn Avail:

No



Image1

Similar: \$13.00

<https://www.target.com/p/90-6oz-glass-round-pitcher-with-handle-threshold-8482/-/A-79474140>

z-glass-round-pitcher-with-handle-threshold-8482/-

/A-79474140

C/S: 13.00

Fee: 0.00

### Inspection/Final Report

<b>Date of Report</b>	:		<b>Date Completed</b>	:	
<b>Type of Report</b>	:	Inspection/Final Report	<b>Expenses</b>	:	\$ 0.00
<b>Inspection Fee</b>	:	\$ 250.00	<b>Tax</b>	:	\$ 0.00
<b>Total C/S</b>	:	\$ 1,908.96	<b>Total Est</b>	:	\$ 300.00
<b>Fees</b>	:	\$ 0.00	<b>Total</b>	:	\$ 250.00
<b>Additional information</b>	:				